

# Condition Report Verification

How can you tell in AS400 if a vehicle has or does not have a CR, vehicle may have a W/O but this does not necessarily mean it has a CR attached.

So how can you tell if someone calls to state CR is missing that it does or does not have a CR?

Go to desired auction location where vehicle is registered to in AS400

Go to GI - 04

```
10/12/16 10:04:23 Global Serial Search 08 USELEC BIGH
Search by Last 6 or 8
BOTH
Last 6 or 8 of VIN: EF157722
```

```
10/12/16 10:04:23 Global Serial Search 08 USELEC BIGH
Search by Last 6 or 8
BOTH
Last 6 or 8 of VIN: EF157722
```

Enter last 6 or 8 of VIN: EF157722 (*preferably last eight*) hit enter on the keyboard to go to the next screen

```
10/12/16 10:07:02 Global Serial Search SERDTA SERCTL BIGH F
Summary Search for Partial VIN EF157722 I
Select Line Number: 01 L
Ln VIN/Status Year Model Seller's Name WO # E
01 1G11C5SL2EF157722 2014 MAL LT CARS GROUP FINANCE & SALES 5428160 V
SF Check or Draft Written Univ. Key 2016-041-020246 Sale Date 10/11/2016
```

```

10/12/16 10:07:02      Global Serial Search      SERDTA SERCTL BIGH F
                        Summary Search for Partial VIN EF157722      I
Select Line Number:      L
Ln VIN/Status      Year Model      Seller's Name      WO #      E
01 1G11C5SL2EF157722 2014 MAL LT      CARS GROUP FINANCE & SALES 5428160 V
SF Check or Draft Written      Univ. Key 2016-041-020246      Sale Date 10/11/2016

```

This screen shows the number of lines available, enter line number, in this case there is only one so enter a 1 and strike enter on keyboard.

```

Reg 10/11/2016 VEH SF - CHECK OR DRAFT WRITTEN (A) Sold 10/11/2016 DISS BIGH
2016 041 02 0246 W 5428160 S L INV 1847765 Y
2014 CHEVROLET MALIBU LT 4DSN TAN TAN 4G Miles 47114
VIN 1G11C5SL2EF157722 Announcements L Y Grp DLR
Lic# Tab# Pd F TR 2 Time Bk 16:38:30 Ck 16:38:37 Alt
Regd RSV jspencer Rg 13:41:27
***** BUYERS SIDE ***** ***** SELLERS SIDE *****
5034041 THE KEY CARS OK 73139 5370051 CARS GROUP FINANCE & SALES
OKLAHOMA CITY HOUSTON TX 77063
Sale price 10,500 Sig 6 Sale Price (Low 11000.00 ) 10,500
Buyers Fee 260 246 Sell Fee (MMR 11250 00 ) 210
Other Adjustments .00 Bid Other Deductions 35.00
Net (HwPd/FT G NEXT ) 10,760.00 Selnet (Ck/Dft# 4 N 706735 ) 10,255.00
=====
Tel 405 300 3607 Disp 00 Ck Id SJOHNSTON Fee 1 Tel 832 891 4195
By Ck# Dep Time 16:41:48 Dep Id ACASTILLO Ck Issued
Deposit Date 10/11/2016 Date Paid 10/11/2016 Ck Cleared
Returned Date Move to Hold Ck S/Pmt
Balance Due .00 Rem from Lot Ck Void
Auctioneer BBA Block Clerk Tracking # 000000000 Ck Sent
Title St # Id Title Sent BU I

```

```

Reg 10/11/2016 VEH SF - CHECK OR DRAFT WRITTEN (A) Sold 10/11/2016 DISS BIGH
2016 041 02 0246 W 5428160 S L INV 1847765 Y
2014 CHEVROLET MALIBU LT 4DSN TAN TAN 4G Miles 47114
VIN 1G11C5SL2EF157722 Announcements L Y Grp DLR
Lic# Tab# Pd F TR 2 Time Bk 16:38:30 Ck 16:38:37 Alt
Regd RSV jspencer Rg 13:41:27
***** BUYERS SIDE ***** ***** SELLERS SIDE *****
5034041 THE KEY CARS 5370051 CARS GROUP FINANCE & SALES
OKLAHOMA CITY OK 73139 HOUSTON TX 77063
Sale price 10,500 Sig 6 Sale Price (Low 11000.00 ) 10,500
Buyers Fee 260 246 Sell Fee (MMR 11250 00 ) 210
Other Adjustments .00 Bid Other Deductions 35.00
Net (HwPd/FT G NEXT ) 10,760.00 Selnet (Ck/Dft# 4 N 706735 ) 10,255.00
=====
Tel 405 300 3607 Disp 00 Ck Id SJOHNSTON Fee 1 Tel 832 891 4195
By Ck# Dep Time 16:41:48 Dep Id ACASTILLO Ck Issued
Deposit Date 10/11/2016 Date Paid 10/11/2016 Ck Cleared
Returned Date Move to Hold Ck S/Pmt
Balance Due .00 Rem from Lot Ck Void
Auctioneer BBA Block Clerk Tracking # 000000000 Ck Sent

Title St # Id Title Sent BU I

```

Once in the vehicle information page in AS4000 do a SF7 this takes you to the CR details page

```

10/12/16 10:13:41 ELECTRONIC CONDITION REPORT DISECR BIGH
WO# 5428160 Universal Key 2016 041 02 0246 ORIGINAL 1
Stock# Account# Group DLR Disposition 00
Seller# 5370051 CARS GROUP FINANCE & SALES Lot Location 702 0
Year Make Model Sub Series Body Color Vin
2014 CHEVROLET MALIBU LT 4DSN TAN 1G11C5SL2EF157722
ENG R TRN PS PB AC EW ES TOP CC EL INT CLR 4X4 TL SRS Date Recd Miles
4G C A X A X X D HT X X B TAN 2 X D 9/23/2016 47114

*--Enter (X) to view detail
S Item Damage Severity Ch Ap SR Hours Amount
X Overall Picture-FRON Overall Picture
] Windshield Star in Glass 1/8" to 1/2" Y 250.00
] Front Bumper Cover Chipped 10 or More Y 4.20 273.00
] Front Bumper Cover Scratch Heavy 1" to 2" Y
] Hood Chipped 6 Y 25.00
] LF Door Mult Dents/No Pa PDR/2 Y 45.00
] LR Door Dent/No Paint Dm PDR/1 Y 45.00
] L Qtr Panel Mult Dents/No Pa PDR/2 Y 45.00
] LR Wheel Curb Rash 8" to 9" Y 55 +
Grand Total 4.20 993.00
Total Approved

```

10/12/16		10:13:41		ELECTRONIC CONDITION REPORT										DISECR BIGH	
WO# 5428160		Universal Key 2016 041 02 0246 ORIGINAL 1													
Stock#	Account#	Group DLR										Disposition 00			
Seller# 5370051	CARS GROUP FINANCE & SALES										Lot Location 702 0				
Year Make	Model	Sub Series			Body	Color	Vin								
2014 CHEVROLET	MALIBU	LT			4DSN	TAN	1G11C5SL2EF157722								
ENG R	TRN PS	PB AC	EW ES	TOP CC	EL INT	CLR	4X4 TL	SRS	Date Recd	Miles					
4G C	A X	A X	X D	HT X	X B	TAN	2 X	D	9/23/2016	47114					
*--Enter (X) to view detail															
<u>S</u>	<u>Item</u>	<u>Damage</u>	<u>Severity</u>	<u>Ch</u>	<u>Ap</u>	<u>SR</u>	<u>Hours</u>	<u>Amount</u>							
X	Overall Picture-FRON	Overall Picture													
	Windshield	Star in Glass	1/8" to 1/2"	Y				250.00							
	Front Bumper Cover	Chipped	10 or More	Y			4.20	273.00							
	Front Bumper Cover	Scratch Heavy	1" to 2"	Y											
	Hood	Chipped	6	Y				25.00							
	LF Door	Mult Dents/No Pa	PDR/2	Y				45.00							
	LR Door	Dent/No Paint Dm	PDR/1	Y				45.00							
	L Qtr Panel	Mult Dents/No Pa	PDR/2	Y				45.00							
	LR Wheel	Curb Rash	8" to 9"	Y				55 +							
									Grand Total	4.20	993.00				
									Total Approved						

Enter an X on the first line to go to the CR information page

10/12/16		10:15:39		ELECTRONIC CONDITION REPORT										DISECRDTL BIGH	
Damaged Item Detail															
ORIGINAL 1															
WO# 5428160	Stock#	Account#										Group DLR			
Seller# 5370051	CARS GROUP FINANCE & SALES										HOUSTON TX				
2014 CHEVROLET	MALIBU	LT			4DSN	TAN	1G11C5SL2EF157722								
Item	0000 00	Overall Picture-FRONT/LFT FRNT													
Damage	00	Overall Picture													
Severity															
Quality															
Action															
Shop															
Chargeable															
Approval															
Sug Repair															
	<u>Repair</u>	<u>Paint</u>	<u>Parts</u>												
Hours				Picture#					Batch#						
Labor\$				Part Cost					Retail						
Notes				Part#											
Vendor															

Damaged Item Detail

ORIGINAL 1

WO# 5428160 Stock# Account# Group DLR  
Seller# 5370051 CARS GROUP FINANCE & SALES HOUSTON TX  
2014 CHEVROLET MALIBU LT 4DSN TAN 1G11C5SL2EF157722

Item 0000 00 Overall Picture-FRONT/LFT FRNT

Damage 00 Overall Picture

Severity

Quality

Action

Shop

Chargeable

Approval

Sug Repair

Repair

Paint

Parts

Hours

Picture#

Batch#

Labor\$

Part Cost

Retail

Notes

Part#

Vendor

Here is where you can tell if there is an active CR, looking at this screen this vehicle does not have a Picture # nor a Batch# therefore there is no CR attached to the listing.